Strip Add 1000

SECTION I - IDENTIFICATION



Win Solutions, Inc. 109 Pine Street Lexa, AR 72355 (800) 489-0470

ChemTel, Inc. :..... (800) 255-3924

Product Number SA1000

Product Name Strip Add 1000

Chemical Family Alkaline Paint Stripper Additive

CAS Number 1310-58-3 **Date Prepared** 7/23/2015

Revision Number

SECTION II - HAZARDOUS IDENTIFICATION

GHS CLASSIFICATION:

Classification

Corrosive to Metals

Category 1

Skin Corrosion/Irritation

Category 3

Sensitization, Respiratory

Category 1

DANGER!

GHS LABEL:





Hazard Statements

H290 May be corrosive to metals
H316 Causes mild skin irritation

H334 May cause allergy or asthma symptoms or breathing difficulties if inhaled

Strip Add 1000

Precautionary Statements

P234 Keep only in original container.

P261 Avoid breathing dust/fume/gas/mist/vapours/spray.

P285 In case of inadequate ventilation wear respiratory protection.

P304+341 IF INHALED: If breathing is difficult, remove victim to fresh air and keep at rest in a position

comfortable for breathing.

P332+313 If skin irritation occurs: get medical advice/attention.

P342+311 Call a POISON CENTER or doctor/physician.

p390 Absorb spillage to prevent material damage.

P404 Store in a closed container.

P501 Dispose of contents/container to an approved waste disposal plant.

SECTION III - COMPOSITION/INFORMATION ON INGREDIENTS

The precise composition of this product is proprietary information. In the event of a medical emergency, a complete disclosure will be provided to medical personnel.

Component Name	CAS#	Component%	OSHA PEL	ACGIH TLV
Caustic Potash, 45%	1310-58-3	<10%	2 mg/m³, Ceiling	2 mg/m³, Ceiling

SECTION IV - FIRST AID MEASURES

Contact with eyes: Flush with water for 15 minutes. Seek immediate medical attention.

Skin contact: Wash exposed areas with water and mild soap. Remove contaminated clothing

immediatelyand launder before reuse. If irritations persist, seek immediate medical

attention.

Inhalation: Remove victim to fresh air. Administer oxygen or artificial respiration if breathing is

affected or stopped. Seek immediate medical attention.

Ingestion: If swallowed. Do not induce vomiting. Seek immediate medical attention.

Give large quantities of water . Never give anything by mouth to an unconsciuous

person.

SECTION V - FIREFIGHTING MEASURES

Suitable Extinguishing Media:

Special Fire Fighting Procedures

Strip Add 1000

Unusual Fire Fighting Hazards:

SECTION VI - ACCIDENTAL RELEASE MEASURES

Personal Precautions: Evacuate all unprotected personnel from the area.

Environmental Precautions: Contain spill if it can be done with minimal risk. Prevent liquid from

entering drains, sewers or waterways. Notify proper authorities.

Methods for Cleaning Up: Take up with absorbent material and place in containers for later

disposal.

SECTION VII - HANDLING AND STORAGE

Handling and Storage:

- Avoid prolonged breathing of mist or vapor. Wash thoroughly after handling.
- Store out of direct sunlight and in a cool, well-ventilated area.
- Aluminum equipment should not be used in the sorage and/or transfer.
 Contact with aluminum parts in a pressurizable fluid system may cause violent reactions.
- Wash thoroughly after handling.
- Avoid contact with eyes.

SECTION VIII - PRECAUTIONS TO CONTROL EXPOSURE / PERSONAL PROTECTION

EXPOSURE LIMITS:

Component Name	CAS#	OSHA PEL	ACGIH TLV
Caustic Potash, 45%	1310-58-3	2 mg/m³, Ceiling	2 mg/m³, Ceiling

Engineering Controls: Adequate local or mechanical to reduce vapor or mist to below the PEL or

TLV.

Monitoring: Wash hands prior to eating, drinking or using the restroom.

Have eye wash stations and safety showers readily available.

Any clothing or shoes which became contaminated with the product should be removed immeadiately and thoroughly laundered before wearing again.

Follow accepted work practices for handling a corrosive material.

Personal Protective Equipment (PPE)

Eye Protection:

Skin Protection:

Strip Add 1000

Respiratory Protection:

SECTION IX - PHYSICAL AND CHEMICAL PROPERTIES		
Appearance	Brown Liquid	
Odor	Light Caustic Odor	
pH@25°C	<14	
Melting/Freezing Point	<32°F Freezing	
Flashpoint	N/A	
Specific Gravity	1.09	
Soluability	Complete	
Auto-Ignition Temperature	None	
Decomposition Temperature	N/A	
VOC Content	N/A	
Odor Threshold	N/A	
Boiling Range	212°F	
Evaporation Point	N/A	
Flammable Limits - Upper	N/A	
Flammable Limits - Lower	N/A	
Vapor Pressure	N/A	
Vapor Density (Air=1)	N/A	
Viscosity	N/A	

SECTION X - STABILITY AND REACTIVITY

Stability: Stable, under normal conditions of storage and handling.

Conditions to Avoid: Acids.

Keep from freezing.

Hazardous Decomposition/Byproducts: None known

Hazardous Polymerization: Will not occur.

Polymerization Conditions to Avoid: None

Incompatibilities: Strong acids and oxidizers

Strip Add 1000

SECTION XI - TOXICOLOGICAL INFORMATION

Likely Route of Exposure: Contact and inhalation; ingestion possible.

Inhalation: Breathing spray or mists can be harmful.

Can cause damage to nasal and respiratory passages.

Eye Contact: Causes eye irritation including stinging, watering and redness which

may result in corneal injury.

Prolonged contact can result in chemical burns and permanent tissue

damage.

Skin Contact: Contact may cause mild sking irritation including redness, burning and

drying/cracking of the skin.

Repeated contact can lead to skin sensitization.

Ingestion: May cause gastrointestinal irritaion with nausea, vomiting and

diarrhea.

Toxicity:

Component Name	LD50	LC50
Caustic Potash, 45%	Oral - Rat - 333 mg/kg	Not Established

Reproductive Effects	Teratogenicity	Mutagenicity	Embryotoxicity	Sensitization to Product	Synergistic Products
Not Applicable	Not Applicable	Not Applicable	Not Applicable	Not Applicable	Not Applicable

SECTION XII - ECOLOGICAL INFORMATION

Ecotoxicity: Information not available.

Mobility: Information not available.

Degradability: Information not available.

BioAccumulation: Information not available.

SECTION XIII - WASTE DISPOSAL CONSIDERATIONS

Observe and follow all federal, state and local regulations.

Strip Add 1000

SECTION XIV - TRANSPORT INFORMATION

DOT SHIPPING INFORMATION

Proper Shipping Name: Compound, Cleaning, Liquid

Contains: Potassium Hydroxide

Hazard Class and Label: 8, Corrosive

Identification Number:

Packaging Group:

SECTION XV - REGULATORY INFORMATION

TSCA STATUS:...... The components of this product are listed on the TSCA Inventory

SARA TITLE III SECTION 302/304 EXTREMELY HAZARDOUS SUBSTANCE:

No chemicals in this material are subject to the reporting requirements.

SARA TITLE III SECTION 311/312 HAZARD CATEGORIZATION:

Acute	Chronic	Fire	Pressure	Reactive
N/A	N/A	N/A	N/A	X

SARA TITLE III SECTION 313 SUPPLIER INFORMATION:

Component Name	CAS#	% by wt.	
	1310-58-3	<10%	

CERCLA SECTION 102(a) HAZARDOUS SUBSTANCE:

Component Name	CAS#	% by wt.	RQ (lbs.)
Potassium Hydroxide	1310-58-3	<10%	1,000

CALIFORNIA PROPOSITION 65:

No chemicals in this material are subject to the reporting requirements.

SECTION XVI - OTHER INFORMATION

Additional:

The information contained in this SDS has been prepared based upon data believed to be reliable, an evaluation of the ingredients in the product, their concentration in the product and potential interactions. The information is offered in good faith and is believed to be reliable and reflects our best professional judgement. Although resonable care has been taken in the preparation of this document, we extend no warranties and make no representations as to the accuracy or completeness of the information contained herein and assume no responsibility regarding the suitability of this information for the user's intended purposed or for the consequence of it's

Strip Add 1000

use. It is furnished to our customer who is urged to study it carefully to become aware of hazards, if any, in the storage, handling, use and disposal of the product; and to insure his/her employee's are properly informed and advised of all safety precautions required. Use or dissemination of all or part of this information for any other purpose is prohibited by law.